

735/737 Feeder Protection Relay

Release Notes

GE Publication Number: GER-4070

Copyright © 2005 GE Multilin

Overview

Summary

• Affected products: 735/737 Feeder Protection Relay

• Date of release: November 18, 2005

Firmware revision: 1.56Hardware revision: D

Release summary

This release note describes the 735/737 Feeder Protection Relay harsh environment option release.

GE Multilin technical support

GE Multilin contact information and call center for product support is shown below:

GE Multilin 215 Anderson Avenue Markham, Ontario Canada L6E 1B3

Telephone: 905-294-6222 or 1-800-547-8629 (North America), +34 94 485 88 00 (Europe)

Fax: 905-201-2098 (North America), +34 94 485 88 45 (Europe)

E-mail: multilin.tech@ge.com

Home Page: http://www.GEmultilin.com

GE Multilin 1

Release details

Modified features

Hardware: added Harsh Environment option

This release includes the addition of the Harsh Environment coating option. This option is for use in sulfur-rich environments such as petroleum and chemical plants, oil refineries, paper and pulp recycling plants, sewer and wastewater plants, and steel mills. The atmosphere produced by various chemical technologies in such facilities causes a serious corrosion problem for many metals used in electrical apparatus. Humidity and temperature variation contributes to the corrosion process leading to electronic equipment failures.

The Harsh Environment coating option:

- protects electronic equipment from corrosive gases
- reduces machines and processes down time
- minimizes equipment maintenance and repair cost

The order code has been changed to introduce the harsh environment option "-H".

Table 1: 735/737 order codes

2 GE Multilin