

TD220MAX Release 1.2.3 Release Notes

TD220MAX Firmware Release 1.2.3 was generated to address functional deficiencies found in the previous 1.2.2 FW release. The FW Release includes:

- A fix for the GPS Sync Jump problem.

FIRMWARE

A bug was found in the TD220MAX Firmware Releases 1.2.2 that effected radios using GPS NMEA and PPS for time synchronization. The bug would cause the radio to occasionally shift one timeslot so that it would transmit messages meant for timeslot 0 in timeslot 1. Due to this bug, the radio might transmit in the wrong timeslot for 1 or 2 seconds and then return to proper timing.