

Software Release Notes

EnerVista Flex Software

Publication Reference: GER-4984

Publication Date: December 12, 2024

Copyright © 2024 GE Vernova. All rights reserved

Table of Contents

1	V1.41 – October 2024	4
1.1	Key new features	4
1.2	Hardware compatibility	4
2	V 1.40 – June 2024	5
2.1	Key new features	5
2.2	Minor Enhancements	5
2.3	Notable bug fixes	5
3	V 1.30 – February 2024	6
3.1	Key new features	6
3.2	Minor Enhancements	6
3.3	Notable bug fixes	6
4	V 1.10 – November 2022	7
4.1	Key new features	7
4.2	Notable bug fixes	7
5	V 1.05 – July 2022	8
5.1	Key new features	8
6	V 1.03 – May 2022	9
6.1	Key new features	9
6.2	Other new features	9
6.3	Notable bug fixes	9
7	V 1.02 – Sep 2021	. 10
7.1	Key new features	. 10
7.2	Other new features	. 10
7.3	Notable bug fixes	. 10
8	V 1.01 – Dec 2020	. 11
8.1	Key new features	. 11
8.2	Other new features	. 11
8.3	Notable bug fixes	. 11
8.4	Hardware compatibility	. 11
8.5	Installation requirements	. 11

8.6	Install	11
8.7	Uninstall	12
8.8	Repairing	12
8.9	Troubleshooting	12
8.10	Upgrade impact	12

1 V1.41 – October 2024

1.1 Key new features

- Software supports migration of Settings from MM300 Settings File (.m30) to MM300-Enhanced Settings File (.CID).
- Software includes a Settings migration Report screen to give details of MM300 to MM300-E Settings migration which can be displayed after migration is performed.
- Settings migration Report can be exported to Excel.
- Software includes an option "Keep me Logged in" at software login. By checking this option, the
 user can avoid logging in multiple times to software at every session.

1.2 Hardware compatibility

- MM300-E
- P40 Agile Enhanced relays. Firmware version below or equal to 05x
- MU360

2 V 1.40 – June 2024

2.1 Key new features

- Device Configuration support added for MM300-Enh device version 2.20.
- User map Settings Configuration screen for MM300-Enh device with version 2.20
- Convert or Upgrade Settings Files (CID files) from lower versions (v2.10) to higher versions (v2.20) and from one order code to another order code with Conversion log screen to report the changes during the conversion
- Support in Software to communicate with MM300-Enh connected over RS485/Gateway to configure Settings, Logic, monitor values, Retrieve Records and Send & Download Settings Files (CID Files)

2.2 Minor Enhancements

- Software Launch page (Dashboard) reorganized.
- Accommodate Projects & Devices widget on Launch Page (Dashboard) to enable easy
 navigation to projects and devices (settings files as CID) without the need to go to project page to
 open a device
- Search and Filter options projects or devices in the widget

2.3 Notable bug fixes

- Firmware upload issues with MM300-Enh
- Enervista Flex unable to open a P40Agile-Enh/MAgile CID file(s) created using D&I Setup Software
- Settings display issues with P40Agile Version 03 devices in Enervista Flex v1.30 Software and related issues with converting version 03 CID files to 05/06 versions of P40Agile/MAgile

3 V 1.30 – February 2024

3.1 Key new features

- Device Configuration support added for P40Agile-Enh/MAgile Devices with firmware versions 05 & 06 for 20TE Models only.
- Convert (Upgrade) Settings Files from Version 03 to Version 05 or 06 to retain the Settings, IEC61850 Configuration and Flex logic
- Power Quality Records Retrieval and display under Records
- Support for additional Protection setting groups 5 and 6

3.2 Minor Enhancements

- Color display of I/O Status for enabled I/O in Monitoring tab
- Quick Switching option provided to switch between Dark and Light color themes of software display

3.3 Notable bug fixes

- Enervista Flex Settings conversion from 02 to 03 causing issue with critical fail relay assignment
- MM300-Enh Devices serial number erasing issue upon firmware upgrade of I/O boards
- Enervista Flex Settings Conversion error when upgrading CID with IEC61850 configuration
- Enervista Flex error in PSL Editor for Virtual I/O with device language set as French
- Enervista Flex displaying Input Signal name text incorrectly with device language set as Russian
- Enervista Flex not allowing to import CIDs from third party devices and thus not allowing subscription of Goose signals in IEC61850 editor

4 V 1.10 – November 2022

4.1 Key new features

 Device Configuration support added for MM300 Enhanced Devices for firmware version 2.10 in both online and offline modes

4.2 Notable bug fixes

- Issue with Settings File conversion of P40Agile Enhanced Devices from version 02 to 03
- Missing GGIO logical nodes for MM300 Enhanced Devices while creating offline settings file
- Missing PFRC, ROCOF logical nodes for P94VB model P40Agile enhanced devices
- Issue with setting the relay operation for output relays for certain P40Agile Enhanced Models when offline settings file is created in Enervista Flex software

5 V 1.05 – July 2022

5.1 Key new features

- Device Configuration support added for P40Agile Enhanced Devices for firmware version 03 in both online and offline modes
- Firmware upload to upgrade the P40Agile Enhanced Devices from Version 02 to Version 03
- Additional setpoints to configure time to operate in User Curves (Flex Curves) which are included in the P40Agile Enhanced Device with firmware version 03 can be configured from software
- Conversion of Settings Files to Version 03 to upgrade configuration of lower Versions 01 & 02 to write to the devices with new firmware version 03, with a detailed Conversion Log

6 V 1.03 – May 2022

6.1 Key new features

- Settings Configuration support added for MM300 Enhanced Devices for Version 200 in both online and offline modes
- Order code options in Version 200 for MM300 Enhanced Devices included in software.
- Quick connect over USB, Serial (RS485) and Ethernet interfaces to work with MM300 Enhanced devices in online mode
- Monitoring the status, metering, and diagnostics data from MM300E Device
- Creation of IEC 61850 configuration using graphical editor
- Logic Designer Editor for creating Flexlogic graphically in both online and offline devices
- Settings file upload and download from the device
- Settings export to Excel, CSV and PDF formats
- Retrieval of records like Events, Disturbance records ,Fault reports, Motor Learned Data and Motor start records
- · Generate Motor Health report in PDF format
- Retrieval of Security Events Log
- Configure Device Users, Role and password to secure the relay
- Execute Commands to the relay
- Generate Service report as zip file
- Quick Setup window to simplify configuration of important device setting without navigating full menu for MM300 Enhanced Device
- Firmware upload of the MM300 Enhanced Device

6.2 Other new features

- Quick Setup window to simplify configuration of important device setting without navigating full menu for P40 Agile Enhanced Deice
- Order code Description window in the Profile page inside the device to understand the device features available for the order code
- Conversion of Settings file across different order codes for P40 Agile Enhanced devices

6.3 Notable bug fixes

Fixes for defects reported in P40 Agile Enhanced devices

7 V 1.02 – Sep 2021

7.1 Key new features

- Configuration support added for Version 02 P40 Agile Enhanced Devices.
- New order code options in Version 02 P40 Agile Enhanced Devices included in software.
- Application support added for Russian & Turkish languages.
- Service Report generation useful to GE technical support staff in any diagnosis or troubleshooting of any relay issues.
- Security Event Log retrieval.
- Logic Editor updated to support Tri-Color LEDs in creating the flexlogic.
- Settings Conversion module to upgrade Version 01 Settings file to higher versions with a detailed conversion log.

7.2 Other new features

- Implementation of Secure Modbus communication & SFTP for P40 Agile Enhanced devices with Basic security option on ethernet interface.
- FCD Subscription implemented in IEC61850 configurator.

7.3 Notable bug fixes

Minor bug fixes in PSL Logic Editor & IEC61850 configurator.

8 V 1.01 – Dec 2020

8.1 Key new features

- · Advanced cybersecurity.
- Protection summary. For quick access to Protection, Monitoring and Control elements.
- Provide capability to configure fixed length GOOSE for P40 Agile Enhanced products.
- PSL SR latch enable and Max 96.
- Launch option for MiCOMS1Agile, UR & 8 Series.

8.2 Other new features

• General performance improvement, plus support for up to 200 devices.

8.3 Notable bug fixes

- In monitoring screen, while refreshing the control automatically moves to top of the screen and user unable to monitor the last item in the screen.
- Progress bar and percentage are not matching while project save/Schema validation.
- Compare Report not highlighting any difference after updating the "Pickup" settings in FlexLogic node.
- Serial number lock field accepting 64 characters, but it should accept 16 characters.
- Unhandled exception issues resolved regarding high memory consumption during IEC61850 and compare operation.
- Imported device always imported at Project level in the canvas.
- After adding a dataset, the device being configured not highlighted after mouse click difficult to see/track which device being configured.
- Other minor bug fixes.

8.4 Hardware compatibility

• P40 Agile Enhanced relays.

8.5 Installation requirements

- Operating System: Microsoft Windows 10 (64 Bit/ 32 Bit), 7 (64 bit).
- Pre-Installation: Uninstall the existing EnerVista Flex version if any.
- Post Installation: You may directly use the EnerVista Flex 1.01 without restarting the system.

8.6 Install

- Make sure the requirements are satisfied.
- Uninstall the previous version of EnerVista Flex.
- Verify that the files are totally removed from Installation Folder: C:\Program Files (x86)\GE Power Management\EnerVista Flex, if not, please remove manually
- Run the installer (EnerVistaFlexSetup101.exe) with admin privileges.
- Note: Right click the EXE and run the same as administrator. Click "Next" in the welcome window.
- Click "Next" in the License/information window.
- Click "Install" on the review window if you are fine with changes of installation.
- Note: Installation may take a couple of minutes.

- Verify that the latest version of EnerVista Flex and its associated tools is present in the Installation Folder.
- Close the window by clicking "Finish."
- Note: Manual restart is not required to complete the installation.

8.7 Uninstall

- Run the installer (EnerVistaFlexSetup101.exe) with admin privileges.
- Click on "Remove" to uninstall the feature.
- Note: Uninstallation may take a 10-15 Minutes.
- Verify that the files are totally removed from Installation Folder: C:\Program Files (x86)\GE Power Management\EnerVista Flex, if not, please remove manually.
- · Close the window.

8.8 Repairing

- Run the installer (EnerVistaFlexSetup101.exe) with admin privileges.
- Check "Repair" to change/update the installation and click "Next."
- Click "Install" on the review window if you are fine with changes of installation.
- Close the window by clicking "Finish."

8.9 Troubleshooting

- Any issues in installation, uninstallation and repairing, may be due to privileges. So, make sure
 the EXE was run with admin privileges. And manually delete the files from Installation Folder
 (C:\Program Files (x86)\GE Power Management\EnerVista Flex), if any failure occurs, before the
 next attempt.
- If either installation or uninstallation fails, use Task Manager to "End Task" the "EnerVista Flex (32 bit)" process and then manually remove the Installation Folder (C:\Program Files (x86)\GE Power Management\EnerVista Flex).
- Perform clean installation of EnerVista Flex 1.10 by uninstalling older versions of EnerVista Flex.

8.10 Upgrade impact

No Known issues.

For product support, contact the information and call center as follows:

Region	E-mail	Comments
Global Contact Centre	ga.support@ge.com	+44 1785 250070
Central and East Asia and Pacific	ga.supportCEAP@ge.com	+61 414 730 964
India	ga.supportIND@ge.com	+91 44 22648000
Middle East, North Africa and Turkey	ga.supportMENAT@ge.com	+971 42929467
Europe, Russia, CIS and Sub-Saharan Africa	ga.supportERCIS@ge.com	+34 94 4858854
North America	ga.supportNAM@ge.com	+1 877 605 6777
Latin America	ga.supportLAM@ge.com	+55 11 36187308