

GE
Grid Solutions

DR60

Version 02AXX

Release Notes

GE Publication Number: Release Notes DR60 FW02A04
Copyright © 2019 GE Grid Solutions.

Overview

This document contains the release notes for DR60 firmware version 02A04, focused on improvements related to Impedance Fault Location and PMU.

Date of release: 04th September 2019

Firmware

Firmware 02A04

Summary

Improvements and issues fixed include the following:

- Improvements in Impedance Fault Locator algorithm to improve accuracy and correctly identify the fault type.
- Changed PMU status behavior to flag PMU frame as invalid if the equipment is not globally synchronized.

Compatibility

DR60 Firmware 02A04 is compatible to configuration software able to deal with configuration version 2.1:

- DR60 Configurator software 02A05 or later;

Upgrade

To upgrade the firmware:

1. Download the desired firmware version from the GE grid solution website (<https://www.gegridsolutions.com/app/Resources.aspx?prod=DR60&type=7>)
2. Open the compatible DR60 Configurator software version
3. Navigate to **Administrative Tools**. This will open a new window and then navigate to the tab **Firmware Update**
4. Select the desired firmware file and press the ok button
5. The software will pop up a window for login
6. Login as **adm** user
7. Wait for the complete upgrade for about 5 minutes and confirm clicking ok

Contact

If you need assistance, please contact our Grid Automation Global Contact Center:

Phone: +44 1785 250070 (United Kingdom)

E-mail: ga.support@ge.com

Website: https://www.gegridsolutions.com/measurement_recording_timesync/catalog/dr60